

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Representatives Present During the Inspection:				
OGM	Karl Houskeeper			
Company	Kon Flook			

Inspection Report

Permit Number:	C0150018			
Inspection Type:	COMPLETE			
Inspection Date:	Monday, July 11, 2011			
Start Date/Time:	7/11/2011 9:00:00 AM			
End Date/Time:	7/11/2011 1:30:00 PM			
Last Inspection:	Monday, June 06, 2011			

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 72 Deg. F InspectionID Report Number: 2795

Accepted by: jhelfric 7/28/2011

Permitee: **ENERGY WEST MINING CO**Operator: **ENERGY WEST MINING CO**

Site: **DEER CREEK MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

8 Total Permitted	19,740.78		
5 Total Disturbed	98.05		
O Phase I	0.60		
Phase II	Phase		
Phase III			

Mineral Ownership

Types of Operations

✓ Federal
✓ Underground

✓ State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

and R. Mouskuper

Date

Monday, July



Permit Number: C0150018
Inspection Type: COMPLETE

Inspection Date: Monday, July 11, 2011

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		✓	
3.	Topsoil	~			
4.a	Hydrologic Balance: Diversions	V		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	Y		~	
4.c	Hydrologic Balance: Other Sediment Control Measures	Y			
4.d	Hydrologic Balance: Water Monitoring	~			
4.e	Hydrologic Balance: Effluent Limitations	✓		~	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	Y			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		~	
8.	Noncoal Waste	✓		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	Y			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.2	a Roads: Construction, Maintenance, Surfacing	✓			
16.t	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	~			
19.	AVS Check	Y			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	~			

Permit Number: C0150018
Inspection Type: COMPLETE

Inspection Date: Monday, July 11, 2011

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/0018 was issued effective 02/07/2011 and expires 02/07/2016.

- -Certificate of Insurance policy number X0720A1A10, issued 08/28/2010 and terminates 08/28/2011.
- -UPDES permit # UT0023604 effective 12/01/2007 and expires @ midnight 11/30/2012.
- -Air Quality permit DAQE-AN0239003-02, issued June 14, 2002.
- -SPCC Plan dated 01/27/2009. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The mine identification signs are located at points of public access to the permit area. The signs contain the required information.

4.a Hydrologic Balance: Diversions

Several diversions (Ditches, Culvert Inlets and rock check dams) need maintenance. Recent storm events over the past week has deposited sediments in the structures thereby requiring maintenance.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2011 sediment pond inspections were done for the main sediment pond and the waste rock sediment pond on March 8, 2011. The Rilda Facilities sediment pond was inspected on March 9, 2011. The inspections were P.E. certiifed on April 12, 2011.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the April and May 2011 discharge monitoring reports. No parameters were exceeded.

7. Coal Mine Waste, Refuse Piles, Impoundments

First quarter 2011 refuse pile inspection was done on March 10, 2011 for the Waste Rock Site. The Elk Canyon and Original Waste Rock Site were inspected on March 8, 2011. The inspections were P.E. certified on April 12, 2011.

8. Noncoal Waste

Minimal noncoal waste (trash) was observed in the parking area. The items were picked up during the inspection and disposed of properly.

20. Air Quality Permit

Approval order AN0239003-02 was issued on 06/14/2002 and remains in effect.

Inspection Continuation Sheet

Permit Number: C0150018
Inspection Type: COMPLETE

Inspection Date: Monday, July 11, 2011

Page 4 of 4

21. Bonding and Insurance

The bond is set at \$4,113,000. It includes the new Rilda Facilities. The bond was recently raised by \$5,000 by the installation of the approved switch gear in Rilda Canyon. There are 19,722.21 permitted acres of which 98.05 are disturbed acres.